



ELECTRICAL MOTOR REPAIR COMPANY

809 E. State Street • P.O. Box 3787 • Trenton, N.J. 08629

(609) 392-6149

elevatormotor.com

Fax (609) 392-7079

SPECIAL INSTRUCTION FOR #7 COUPLER

“DON’T PINCH POLY”. SET A 7/8 GAP BETWEEN THE TWO METAL HALVES AT 12, 6, 3 AND 9 OCLOCK AS TO MAKE TO METAL HALVES SQUARE WITH EACH OTHER (1” MAX). TIGHTEN 2 ALLEN SET SCREWS TO 35 FOOT LBS PER TAPER LOCK INSTRUCTIONS IN INSTRUCTION BOOKLET.

IMPERIAL
ELECTRIC



Westinghouse

LS LEROY
SOMER

IMO

IMO Pump Division